


**SINGER**  
**131W113**

orm 2805w  
542 )  
rinted in U. S. A.


# SINGER

## 131w113




**THE SINGER MANUFACTURING COMPANY**

16615 - 1/2




16643 - 3/8

228368




17080 - 5/8




17105 - 5/8


236139



236121



223855




236079

200056E


247623

213037



236070

235864



236087

204243

200900H

200555H



235866



200383C

200034C


235865

235865


200034C

17106 - 5/8


236135



236121



223855




236079


200056E

247623

213037



235864



236087

204243

200555H



235866



200383C

200034C


235865

200034C


235865




17110 - 1/2




17126 - 1/6





17127 - 3/8




17128 - 3/8










17131 - 1/2




17132 - 3/8







17134 - 3/8




17136 - 5/8



17137 - 1/2



17138 - 5/8



17139 - 1/3



237044